

NTSB-RE-30 Materials Laboratory

Brian Young

490 L'Enfant Plaza E. SW

Washington, DC 20594

Saybolt Petroleum Services A Core Laboratories Company

201 Deerwood Glen Dr Deer Park, TX 77536 281-478-1300

Report Number: 13071- 160565

Date Reported:

2/26/2016

Date Received:

2/19/2016

Analytical Report

Sample No.: 160565-001 Sample ID 26732-MVEL Faro

Date Sampled 9/8/2015

Blount Island Terminal (B-201/Nustar)

Test	Result	Units	Method	Minimum	Maximum
Flash Point, PMCC	196	Deg F	ASTM D-93B	140	
Kinematic Viscosity	38.45	cSt @ 100 C	ASTM D-445	15	50
Sediment by Extraction	0.02	Wt %	ASTM D-473		0.5
Water by Distillation	0.05	LV %	ASTM D-95		1
Water & Sediment	0.07	Wt %			2



Saybolt Petroleum Services A Core Laboratories Company

201 Deerwood Glen Dr Deer Park, TX 77536 281-478-1300

NTSB-RE-30 Materials Laboratory

Brian Young

490 L'Enfant Plaza E. SW Washington, DC 20594

Report Number: 13071- 160565

Date Reported:

2/26/2016

Date Received:

2/19/2016

Analytical Report

Sample No.: 160565-002 Sample ID 76017-EL Faro

Jax, FI (B-2010

Date Sampled 9/21/2015

Test	Result	Units	Method	Minimum	Maximum
Flash Point, PMCC	194	Deg F	ASTM D-93B	140	
Kinematic Viscosity	36.57	cSt @ 100 C	ASTM D-445	15	50
Sediment by Extraction	0.01	Wt %	ASTM D-473		0.5
Water by Distillation Water & Sediment	0.10 0.11	LV % Wt %	ASTM D-95		1 2

The analytical results, opinions, or interpretations contained in this report are based upon information and material supplied by the client for whose exclusive and confidential use this report has been made. The analytical results, opinions, or interpretations expressed represent the best judgement of Saybolt Petroleum Services. Saybolt Petroleum Services, however, makes no warrant or representation, express or implied, of any type, and expressly disclaims same with which such report is used or relied upon for any reason whatsoever. Any person relying upon this report should be aware that issuer's activities are carried out under their general terms and conditions. Page 2 of 3



201 Deerwood Glen Dr Deer Park, TX 77536

281-478-1300

NTSB-RE-30 Materials Laboratory

Brian Young

490 L'Enfant Plaza E. SW Washington, DC 20594

Report Number: 13071- 160565

2/26/2016 Date Reported:

Date Received: 2/19/2016

Saybolt Petroleum Services A Core Laboratories Company

Analytical Report

Sample No.: 160565-003 Sample ID 76162-EL Faro

Jax, Fl (B-2010

Date Sampled 9/14/2015

Test	Result	Units	Method	Minimum	Maximum
Flash Point, PMCC	196	Deg F	ASTM D-93B	140	
Kinematic Viscosity	38.45	cSt @ 100 C	ASTM D-445	15	50
Sediment by Extraction	0.01	Wt %	ASTM D-473		0.5
Water by Distillation	0.05	LV %	ASTM D-95		1
Water & Sediment	0.06	Wt %			2

Approved By: Larry Scott Laboratory Manager